Are Your F.O. Cleaning Materials on the Job Site?

RDOF

The Job is Not Done Until It's Clean.

- 85% of new connectors have plasticizer off-gas residue or are dirty from the job site.
- It's mission critical that connector end faces are pristine prior to mating.





Check out Sticklers new E-Guide, The Juice, and learn more about why Sticklers is your go-to for F.O. cleaning @ MicroCare.com/SticklersTools



MCC-FK08
Sticklers™ High-Volume Cleaning Kit
Contains everything you need for 2,300+
perfectly clean connectors.



Order Today! 888-644-6075 tvcinc.com



